

Title:

Thru-Wall Scupper Flashing

Number:

PG-LF-DRAIN-03

Revised:

March 2020

Notes:

- Cleaning and Preparation - Clean and prepare the surface by brooming, mild detergent & water rinse or as required to remove any conditions that could adversely affect adhesion of primers and liquid materials.
- PG Flashing System consists of the following:
 - PolyBrite base coat
 - PolyBrite reinforcing fabric
 - PolyBrite saturation coat
 - PolyBrite surface coats
- Illustration and notations intended for generalized applications only. Please refer to Product Data Sheets for additional information.
- Urethane sealant for terminations shall be compliant with ASTM C920.

