

Title:  
**Thru-Wall  
Scupper Flashing**

Number:  
**PG-LF-DRAIN-04**

Revised:  
**March 2020**

Notes:

- Cleaning and Preparation - Clean and prepare the surface by brooming, mild detergent & water rinse or as required to remove any conditions that could adversely affect adhesion of primers and liquid materials.
- Surfaces to receive PG Flashing System should be primed with Polybrite 745.
- PG Flashing System consists of the following:
  - PolyBrite base coat material
  - Polybrite Polyester Fabric
  - Polybrite surface coat material
- Illustration and notations intended for generalized applications only. Please refer to Product Data Sheets for additional information.
- Any urethane sealant for terminations shall be compliant with ASTM C920.

