

Technical Bulletin #2025-02

TO: All POLYGLASS Polystick Users
CC: POLYGLASS Sales & Technical Services
RE: Guidance regarding Color variations on granulated membranes

Polyglass provides the following guidance regarding occasional color variations observed on the granulated surface of our roofing membrane products.

Color differences may occur between rolls, within a single roll, or develop over time due to environmental exposure such as ultraviolet light, air pollution, and moisture. These variations are common among all granulated roofing membranes and are considered a normal characteristic of the product.

The most common causes of granule surface color variation include:

- Manufacturing processes and batch-to-batch differences in raw materials
- Natural effects of weathering and aging in the field
- Storage and handling conditions prior to installation

It is important to note that these color variations are cosmetic only and have no impact on the performance, quality, or long-term durability of the membrane system. For this reason, surface color inconsistencies are not considered a defect and are not covered under the terms of the Polyglass Limited Warranty.

Polyglass recommends informing building owners, architects, and other stakeholders in advance that color variation is a normal and expected aspect of granulated roofing membrane production and exposure.

For more detailed application or warranty inquiries, please contact the Polyglass Technical Services Department at 866-794-9659 or via email at Technical@Polyglass.com.

