

EXPANSION JOINT FLASHING DETAIL

SURFACE PREPARATION

NUMBER:

PG-EJD-007

DATE:

NOVEMBER 2016

ALL SURFACES SHALL BE CLEAN, DRY, AND FREE OF ANY DIRT, DUST, GRAVEL, OIL, SURFACE CHEMICALS OR OTHER CONTAMINANTS THAT MAY INTERFERE WITH OPTIMUM ADHESION. POLYGLASS RECOMMENDS AN ADHESION TEST PRIOR TO COATING APPLICATION. IF ADHESION TEST FAILS,

ADDITIONAL CLEANING AND/OR PRIMING MAY BE REQUIRED.



www.polyglass.com