TECHNICAL BULLETIN

POLYGLASS USA Inc. Corporate Office 1111 West Newport Center Drive Deerfield Beach, Florida 33442 Tel. (954) 233-1330 - Fax: (954) 418-4453

> Email: technical@polyglass.com Website: www.polyglass.com

Technical Bulletin #2018-07

TO: All **POLYGLASS** Distributors & Users

CC: POLYGLASS Sales & Technical Services

Date: December 18, 2018

Author: James E. Akins,

National Technical Services Manager

RE: Recommended cleaning process for Polyfresko G membranes

In our efforts to provide support to our distributors and stock holders of Polyglass products, we would offer the following guidelines to assist in the cleaning of all Polyfresko G products (APP, SBS or SA), should an over accumulation of algae occur or other incidental soiling.

Polyglass recommends that a solution of bleach and water, be used and applied thru a hand pump sprayer (H.D. Hudson sprayer, aka garden sprayer). The bleach to water solution shall be 40% bleach to 60% water. Please take care in using the bleach products as prescribed in their instructions, as Polyglass will not be accountable for failure to prescribe to those instructions.

After spraying solution directly to and wetting the surface, you may use some light brushing/brooming if you deem necessary. Let it sit for several hours and then hose off with standard garden hose pressure. Excessive pressure may result in damage to the products surface, if not monitored accordingly.

Be sure all cleaning solution and water drains properly, to meet and maintain the requirements of the Polyglass Warranty, with regards to bird baths and ponding water.

Special circumstances and questions can be addressed to the POLYGLASS Technical Services Department.

12/18/2018 IEA

