

Title:  
**Field Fabricated Pipe  
Penetration Flashing**

Number:  
**PG-LF—PEN-10**

Revised:  
**March 2020**

- Notes:
- Cleaning and Preparation - Clean and prepare the surface by brooming, mild detergent & water rinse or as required to remove any conditions that could adversely affect adhesion of primers and liquid materials.
  - Surfaces to received Polyflash 1C Flashing System may need to be primed, depending on the substrate.
  - Polyflash 1C Flashing System consists of the following:
    - Polyflash 1C base coat
    - Polybrite Fabric
    - Polyflash 1C surface coat
  - Illustration and notations intended for generalized applications only. Please refer to Product Data Sheets for additional information.
  - Urethane sealant for terminations shall be compliant with ASTM C920.
  - PG recommends that all metal flashings in connection with PG Flashing System shall be designed and installed in compliance with ANSI/SPRI ES-1.

